5. IMPROVEMENT OF THE RUBBER SEALS ON THE MOWING DECK COVERS

- The original rubber seals on the covers have been replaced with a new type that includes a "bulb" which closes the spaces between the covers providing better protection against grass, dirt and dust.
- > This change also helps extending the lifespan of the belts and bearings on the mowing deck.





NEW RUBBER SEAL WITH "BULB"








NEW RUBBER SEAL WITH "BULB"

6. NEW STEERING SERVO (ILD02)

> Allows faster and more comfortable steering







DVOŘÁK – svahové sekačky s.r.o. www.slope-mower.com



Spider Innovations 2019



ALL TERRAIN, ALL GRASS, ALL PEOPLE



CLUTCH BELT TENSIONER | ENGINE OIL DRAIN HOSE | NEW SENSORS FOR

CUTTING HEIGHT SETTINGS | IMPROVED RUBBER SEALS OF THE MOWING DECK

COVERS | NEW STEERING SERVO AND UPDATED WINCH

1. CLUTCH BELT TENSIONER (ILD02)

- > Thanks to the new tensioner system in combination with the new Optibelt Super TX 1160LP, manual tensioning is not needed as often anymore. Belt vibrations are reduced to a minimum thus extending its lifespan significantly.
- > It is possible to retrofit the belt tensioner on older machines. (see PPI-121 for more information)







2. ENGINE OIL DRAIN HOSE (ILD02)

- > Hose with cap added
- > No more necessity to pump the oil out.
- > It is possible to retrofit the oil drain hose on older machines with some small adjustments. (see PPI-122 for more information)







 ORIGINAL VERSION OF THE MACHINE HAS THE PLUG ON THE ENGINE WITHOUT THE OIL DRAIN SYSTEM.

3. UPDATED STABILIZING WINCH (ILD02, ILD01)

- > Bigger, stronger chain, new side covers of the bearings, longer lever of the winch guiding frame.
- > The bigger, stronger chain and sprocket ensure less wear on the winch.
- > The new bearing cover design makes maintenance easier and improves bearing protection.
- > The longer lever on the winch guiding frame forgoes the damage caused by the pinching between the frame and the winch side bracket.
- > Slight angling of the holes makes chain tensioning easier.
- > The entire winch has been updated. Although its single components cannot be retrofitted on older winch models, the complete new winch can be retrofitted on all older Spider models.







↑ EASIER CHAIN

4 NEW TYPE OF THE SENSORS (ILD02)

- > Improved component life expectancy.
- > Reduced cutting height control failure rate.



